





LZ



Roltechnik s.r.o.; Czech Republic, 56933 Třebořov 160,
tel.: +420 461 324 301/302, fax: +420 461 324 297,
<http://www.roltechnik.com>; e-mail: objednavky@roltechnik.cz




2017/09/13
Rev.:01
MA6327

LZC01+LZ



LZC01+LZ SET		
TYP	Y (MIN-MAX) mm	C (mm)
800	780-815	690
900	880-915	790
1000	980-1015	890

LZD01+LZ



LZD01+LZ SET

TYP	Y (MIN-MAX) mm	C (mm)	S (mm)
800	780-815	510	243-268
900	880-915	510	343-368
1000	980-1015	610	343-368
1100	1080-1115	610	443-468
1200	1180-1215	710	443-468

28. 1x
P4091



29. 1x
P4090



30. 1x
M8169




11. 1x
MA5937



17. 3x
M0811
n3,9x38



18. 3x
M0511



19. 3x
M0806
n3,5x9,5



20. 3x
M1907



21. 1x
M0808
n3,5x9,5




22. 3x
M0768




23. 1x
M0838
n2,8




13. 1x
MA5531




31. 1x
MA5532




32. 1x+1x
MA5534




MA5535







A 3x


28




E 6x




B




D




B 6x



C





C 6x



E

D 6x






LZ + LZD01

Sehen Montageanleitung LZD01
See installation instructions LZD01
Dle montážního návodu LZD01






LZD01





LZ + LZC01

Sehen Montageanleitung LZC01
See installation instructions LZC01
Dle montážního návodu LZC01


LZC01



J








J







30

J









N

N

SILICONE

100mm

